


Billet Gas Cap 2.0/3.0



© 2024 RJWC Powersports AB

Billet Gas Cap 2.0/3.0

Gas Cap Important Information

- When installing the Gas Cap, you do not need to overtighten it, if you overtighten the Gas Cap, you risk damaging the nitrile rubber gasket.
- No tools need to be used to tighten the Gas Cap, just use your hand.

Parts Included

Gas Cap

Need help? Got a question?

Get in touch at support@rjwc.se or your closest RJWC Dealer.

© 2024 RJWC Powersports AB

Billet Gas Cap 2.0/3.